DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-013796 Address: 333 Burma Road **Date Inspected:** 21-Apr-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** Segment

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, M.Manikandan was present during the time noted above for observations relative to the work being performed.

OBG # TRIAL ASSEMBLY YARD

This QA inspector performed dimensional check along with ABF on U-Rib using 1M straight edge to check offset for below segment. Reports forwarded to team leader for further action

7DE-7EE

OBG # TRIAL ASSEMBLY YARD

This QA inspector performed dimensional check along with ABF on U-Rib using 1M straight edge to check offset for below segment. Reports forwarded to team leader for further action

7EE-8AE

OBG # TRIAL ASSEMBLY YARD

This QA inspector performed dimensional check on deck panel diaphragm using 710mm straight edge and right angle to check plumpness and flatness for below segment. Reports forwarded to team leader for further action

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

8BW -PP 65, PP 66 and PP 67 8CW -PP 68, PP 69, PP 70 and PP 71

OBG # TRIAL ASSEMBLY YARD

This QA inspector performed dimensional check on floor beam using 1.5M straight edge to check flatness for below segment. Reports forwarded to team leader for further action

Lift 8W

Lift 7W

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact, who represents the Office of Structural Materials for your project.

Inspected By:	Manikandan, Murugan	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer